

## APPENDIX A

### BOARD APPOINTMENT MEMORANDUM



The Secretary of Energy  
Washington, DC 20585

March 21, 2000

MEMORANDUM FOR: RICHARD E. GLASS, MANAGER  
ALBUQUERQUE OPERATIONS OFFICE

FROM: BILL RICHARDSON *BR*

SUBJECT: Type A Accident Investigation of the  
March 16, 2000, Radiological Event at TA-55,  
Los Alamos National Laboratory

I hereby establish a Type A Accident Investigation Board to investigate the March 16, 2000, radiological contamination and intake event at Technical Area 55, Los Alamos National Laboratory. I have determined that it meets the requirements for a Type A investigation consistent with DOE Order 225.1A, *Accident Investigations*.

The Office of Oversight within the Office of Environment, Safety and Health will lead the investigation. I appoint Thomas Rollow as the Accident Investigation Board Chairperson from the Office of Oversight. The Board will be composed of the following members: Peter O'Connell, Worker Protection Programs and Hazards Management; Douglas Minnema, Defense Programs; Ali Ghovanlou, Independent Oversight Performance Assurance; John Eschenberg, Savannah River Operations Office; Michael Cornell, Oakland Operations Office; and Isaac Valdez, Albuquerque Operations Office. I have been assured that these individuals do not have "direct line management responsibility for day-to-day operation or oversight of the facility, area, or activity involved in the accident." The Board will be assisted by advisors and other personnel as deemed necessary by the Board Chairperson.

The scope of the Board's investigation will include, but is not limited to, analyzing causal factors, identifying root causes resulting in the accident, and determining Judgments of Need to prevent recurrence. The investigation will be conducted in accordance with DOE Order 225.1A. The Board will examine safety management systems, including management roles and responsibilities and application of lessons learned from similar type accidents within the Department. The investigation and analyses will be conducted within the framework of the Department's Integrated Safety Management Policy to assure maximum benefit to improving safety and sharing lessons learned throughout the complex.



The Board will provide the Assistant Secretary for Environment, Safety and Health with periodic reports on the status and progress of the investigation. These reports should not include any findings or arrive at any premature conclusions until an analysis of all the causal factors have been completed. Discussions of the investigation and copies of the draft report will be controlled until I accept and authorize release of the final report. The final report should be provided to my office by April 21, 2000.



cc:



T.J. Glauthier, DS  
D. Michaels, EH-1  
T. Rollow, EH-2  
S. David Stadler, EH-2  
R. Hardwick, EH-2  
J. Fitzgerald, EH-5  
T. Gioconda DP-1  
G. Podonsky, OA-1  
G. Rudy, SR  
J. Turner, OAK  
C. Longenbaugh, AL AI POC


# APPENDIX B

## EVENTS AND CAUSAL FACTORS CHART









## APPENDIX C

### BARRIER ANALYSIS

| Hazard: Airborne Contamination   |                               | Target: Worker  |   |
|--|-------------------------------|---|---|
| What were the barriers?  | How did each barrier perform? | Why did the barrier fail?   | How did the barrier affect the accident?  |
| Radiation hand monitors (Ludlum Model 214)   | Not Used                      | Responded as designed; RCT response to alarm was a missed opportunity.  | May have caused an increased severity in the consequences.  |
| Continuous air monitors  | Failed                        | Sampling locations for air monitors not positioned in optimal location for maximum personnel protection.  | Repositioning of samplers may have reduced the exposure time of all but one of the workers; minimal impact on the individual with maximum exposure.   |
| Mechanical pipe fitting integrity  | Failed                        | Mechanical compression fitting on the dry vacuum line was not properly tightened during installation.   | Failure of the fitting resulted in the release of contamination from internally contaminated piping when argon valve was opened.  |
| Header isolation valves  | Failed                        | Argon header isolation valve was open. Valve operation is prevented by memo only and has limited applicability. There is no valve line-up checklist or policy on valve operation.   | Isolation between a contaminated pipe and a pressure source was compromised.  |
| Vacuum manifold valve  | Failed                        | Valve operating surface (Teflonâ) deteriorated due to thermal, abrasion, and/or radiation damage.   | Dry vacuum valve could not isolate argon pressurization of the manifold from the dry vacuum piping and the failed mechanical fitting.   |
| Respiratory Protection Program   | Not Used                      | Potential hazard was not addressed, and appropriate PPE was not utilized.   | Lack of respirator resulted in an increase in the total intake by affected workers.   |
| Configuration Control:<br>a) Piping and valves;<br><br>b) Valve alignment,<br><br>c) Valve labeling; Operator Aids<br><br>d) Procedures, piping and electrical drawings, system lineup | Not Used                      | a) Piping and valves are not installed per Field Change Request.<br><br>b) System valve alignment is not defined.<br><br>c) Valves are not labeled for function, or operation; No placards or postings to provide assistance in system operation.<br><br>d) Piping and electrical drawings are not current to the as built condition of the support systems for the glovebox. | Field design change identified the need for gate valves, thus limiting the pressurization rate of the vacuum line.<br><br>Proper component identification (labeling) would have identified that the lines being evaluated were not part of the assigned task.<br><br>Valve labeling would have informed the worker that manifold valves were not for the glovebox.<br><br>Lack of an operating procedure and a documented valve lineup for the airlock manifold valves may have caused piping pressurization.   |
| Standards, Procedures and Permits – RWP, SWP, SOP, Safety Manual.<br><br>• Work planning;<br><br>• Work control  | Failed                        | Procedure TA55-SOP-555.R4, which defines the baseline safety envelope for radiological control at TA-55, was the only work control procedure; it was not adequate for the task, nor was it intended for this work.<br><br>Skill of worker operations were allowed since no standards existed.   | Lack of work planning, hazards analysis, and hazard controls allowed an activity that affected mechanical joints in a contaminated system without proper protection. There is no uniform understanding of what activities are, or are not, allowed under this procedure.<br><br>A standards or procedure-based approach would have identified the hazards and established controls to limit the risk associated with those hazards which management would have approved. This task relied upon the skill of the workers involved without clear limitations on their actions or an understanding of the consequences of those actions. |

| Hazard: Airborne Contamination  |                               | Target: Worker   |   |
|---|-------------------------------|--|---|
| What were the barriers?   | How did each barrier perform? | Why did the barrier fail?  | How did the barrier affect the accident?  |
| Training and Qualifications   | Failed                        | Workers did not understand the potential hazards, did not understand system design and operation (purpose of certain valves and piping runs).  | Worker's knowledge was not commensurate with the assigned responsibility or with actions taken. More thorough knowledge of piping systems might have prevented the actions taken.   |
| Quality Assurance of Piping Installation  | Failed                        | <p>The piping and components in the manifold were not installed per Field Change Request to minimize overpressurization.</p> <p>There is no documentation that the mechanical compression fittings were tested after installation.</p>   | <p>Failure to install the piping in the design configuration contributed to confusion on valve operations. Component changes (as-built vs. as-designed) increased the probability of high pressures affecting the vacuum system piping.</p> <p>Failure to test the mechanical compression fittings allowed an improperly installed fitting to go undetected.</p>  |
| Lessons Learned   | Failed                        | <p>Multiple lessons learned opportunities (ORPS, LANL and TA-55 bulletins, RIRs) were not communicated to the worker level.</p> <p>Previous occurrence evaluations did not determine the direct cause; i.e., source of the contamination, to ensure the proper correctives were developed.</p>   | <p>Workers could not benefit from the lessons learned from precursor contamination events; the potential for residual contamination; or the potential for and consequences of shaking piping to look for failed connections.</p> <p>The November 19, 1998, occurrence investigation for the same glovebox did not thoroughly evaluate the source of the contamination, nor identify the leaking mechanical fitting.</p>   |
| Hazard Analysis<br>a) For electrolytic decontamination<br><br>b) For maintenance evaluation | Failed                        | <p>a) The electrolytic decontamination hazard analysis for this box was limited to the HA performed for previous glovebox decontamination efforts. The HA did not identify the differences between the Pu-239 and Pu-238 glovebox designs and operations.</p> <p>b) Did not evaluate the possible consequences of pipe shaking or valve operation while evaluating the loss of argon flow to the glovebox.</p> | <p>a) High humidity from decon operations may have shorted the glovebox power receptacle. The resulting trip of the breaker in circuit #10 led to isolation of the solenoid valve in the glovebox argon supply line. Lack of argon flow is what generated the request for a maintenance evaluation.</p> <p>b) Past experience with mechanical joint failures leading to contamination should have resulted in additional hazard controls when shaking piping systems or operating valves.</p> |
| Technical Basis Documents   | Failed                        | The Facility Hazard Analysis (subset of the SAR) does not analyze the risk (probability and consequence) of either a positive pressure scenario resulting in an airlock or vacuum line leak. The HA does not analyze the risk to workers associated with failures in various auxiliary systems.  | Lack of an evaluation of these auxiliary systems limits the knowledge and understanding of the facility in setting operational limits and understanding the consequences of certain accident situations. The release of Pu-238 from the dry vacuum line may have been prevented if this scenario was evaluated.   |



| Hazard: Airborne Contamination   |                               | Target: Worker  |   |
|--|-------------------------------|---|---|
| What were the barriers?  | How did each barrier perform? | Why did the barrier fail?   | How did the barrier affect the accident?  |
| Communications<br>a) Work control<br><br>b) Troubleshooting activities<br><br>c) Tripping of circuit #10 | Failed                        | a) AWS and RWS did not communicate unusual conditions associated with the glovebox.<br><br>b) Scope of the task for the argon flow evaluation was not communicated to the RCT.<br><br>c) Technicians did not communicate the status of circuit #10 to each other. | Lack of adequate communication did not provide the workers or supervisors with the needed information to properly investigate the failures associated with circuit #10 or argon flow. |
| System Design  | Failed                        | 1) Selection of improper material for valve seats (Teflon®) in a contaminated system.<br><br>2) Over reliance on the use of compression fittings.   | Valve seat leakage and an incorrectly assembled compression fitting resulted in the release of contamination.   |

## Tables, Figures, and Exhibits

### Tables

|             |   |    |
|-------------|---|----|
| Table ES-1. | Causal Factors and Judgments of Need .....  | 4  |
| Table 2-1.  | Time and Objectives of Each Reentry to the Room .....   | 17 |
| Table 2-2.  | Preliminary Dose Estimate (CEDE) to Affected Workers .....  | 21 |
| Table 3-1.  | Deficiencies in the Application of the Core Functions<br>of Integrated Safety Management Related to the TA-55 PF-4 Accident ..... | 39 |
| Table 3-2.  | Barrier Analysis Summary .....  | 40 |
| Table 3-3.  | Change Analysis .....   | 41 |
| Table 3-4.  | Causal Factors Analysis Summary .....   | 42 |
| Table 4-1.  | Causal Factors and Judgments of Need .....  | 46 |

### Figures

|             |  |    |
|-------------|--|----|
| Figure 2-1. | Locations and Exit Paths of Workers .....  | 8  |
| Figure 2-2. | Airlock Manifold Piping Diagram .....  | 11 |
| Figure 2-3. | Fixed-head Air Sampler Results in Room .....                                     | 18 |
| Figure 2-4. | Northwest Corner of the Glovebox, Including the Argon and Dry Vacuum Lines ..... | 20 |

### Exhibits

|              |   |    |
|--------------|---|----|
| Exhibit 1-1. | Aerial Photo of Plutonium Facility .....                          | 6  |
| Exhibit 2-1. | Affected Line of Gloveboxes .....                                 | 9  |
| Exhibit 2-2. | Glovebox Bubbler .....  | 10 |
| Exhibit 2-3. | Alignment of Valves in the Manifold Line after the Accident ..... | 19 |
| Exhibit 2-4. | Components of Finger-Tight Fitting .....                          | 22 |
| Exhibit 3-1. | Teflon® Seat Degradation .....                                    | 34 |

## Abbreviations Used in This Report

|                 |  |
|-----------------|--|
| <b>AAMFO</b>    | <b>LAAO Assistant Area Manager for Facility Operations</b>   |
| <b>AC</b>       | <b>Alternating Current</b>   |
| <b>AL</b>       | <b>DOE Albuquerque Operations Office</b>   |
| <b>ALARA</b>    | <b>As Low as Reasonably Achievable</b>   |
| <b>Anti-C</b>   | <b>Anti-Contamination Clothing</b>   |
| <b>AWS</b>      | <b>Area Work Supervisor</b>  |
| <b>CAM</b>      | <b>Continuous Air Monitor</b>  |
| <b>CDE</b>      | <b>Committed Dose Equivalent</b>   |
| <b>CEDE</b>     | <b>Committed Effective Dose Equivalent</b>   |
| <b>CFR</b>      | <b>Code of Federal Regulations</b>   |
| <b>CPT</b>      | <b>Chemical Process Technician</b>   |
| <b>CT</b>       | <b>Chemical Technician</b>   |
| <b>DCP</b>      | <b>Design Change Package</b>   |
| <b>DNFSB</b>    | <b>Defense Nuclear Facilities Safety Board</b>   |
| <b>DOE</b>      | <b>U. S. Department of Energy</b>  |
| <b>DP</b>       | <b>DOE Office of the Deputy Administrator for Defense Programs</b>                                     |
| <b>DTPA</b>     | <b>Diethylenetriaminepentaacetate</b>  |
| <b>EH</b>       | <b>DOE Office of Environment, Safety and Health</b>  |
| <b>EM&amp;R</b> | <b>Emergency Management &amp; Response</b>   |
| <b>EPA</b>      | <b>U. S. Environmental Protection Agency</b>   |
| <b>ESH</b>      | <b>Environment, Safety and Health Group</b>  |
| <b>ES&amp;H</b> | <b>Environment, Safety, and Health</b>   |
| <b>ET</b>       | <b>Electrical Mechanical Technician</b>  |
| <b>FCR</b>      | <b>Field Change Request</b>  |
| <b>FMU</b>      | <b>Facility Management Unit</b>  |
| <b>HEPA</b>     | <b>High Efficiency Particulate Air</b>   |
| <b>HPAL</b>     | <b>Health Physics Analytical Laboratory</b>  |
| <b>ISM</b>      | <b>Integrated Safety Management</b>  |
| <b>LAAO</b>     | <b>Los Alamos Area Office</b>  |
| <b>LANL</b>     | <b>Los Alamos National Laboratory</b>  |
| <b>LIG</b>      | <b>Laboratory Implementing Guideline</b>   |
| <b>LIR</b>      | <b>Laboratory Implementing Requirement</b>   |
| <b>LPR</b>      | <b>Laboratory Procedure Requirement</b>  |
| <b>LRRI</b>     | <b>Lovelace Respiratory Research Institute</b>   |
| <b>MOU</b>      | <b>Memorandum of Understanding</b>   |
| <b>NMT</b>      | <b>Nuclear Material Technology Division</b>  |
| <b>NNSA/DP</b>  | <b>National Nuclear Security Administration of the U.S. Department of Energy/<br/>Defense Programs</b> |
| <b>ORPS</b>     | <b>Occurrence Reporting and Processing System</b>  |
| <b>RCT</b>      | <b>Radiological Control Technician</b>   |
| <b>RWP</b>      | <b>Radiological Work Permit</b>  |
| <b>RWS</b>      | <b>Room Work Supervisor</b>  |
| <b>SAR</b>      | <b>Safety Analysis Report</b>  |
| <b>SCBA</b>     | <b>Self-Contained Breathing Apparatus</b>  |
| <b>SOP</b>      | <b>Safe Operating Procedure</b>  |
| <b>SOW</b>      | <b>Statement of Work</b>   |
| <b>SWP</b>      | <b>Special Work Permit</b>   |
| <b>TA</b>       | <b>Technical Area</b>  |
| <b>TEDE</b>     | <b>Total Effective Dose Equivalent</b>   |
| <b>TSR</b>      | <b>Technical Safety Requirement</b>  |
| <b>UC</b>       | <b>University of California</b>  |